**GE Gas Power** 

# Agenda

- Register Single Sign on with GE
- Requesting clear orbit access
- Forgot User ID?
- Forgot Password?
- P28A-AL-0002 Key Elements for SDR & RFI Process
- ClearOrbit Overview
- Sourcing Contact Details

# **Register Single Sign on with GE**

#### Step 1

✓ Open URL <a href="https://registration.gepower.com/registration/">https://registration.gepower.com/registration/</a>

### Step 2

✓ Click on the **Register** 

#### Step 3

- ✓ Update the Basic and Mandatory Information
- ✓ Ensure to find <a>o</a> on all mandatory fields rather than <a>O</a>
- $\checkmark$  If  $\bigcirc$  recheck the fields and update

### Step 3.1

- ✓ Answer country information for security reasons
- ✓ Check
  - ✓ I confirm that the information I have provided is accurate and that I am currently employed by the company I have listed above.
  - ✓ I agree to GE's Terms and Conditions
  - ✓ Click or touch the image mentioned
- ✓ Click Submit
- ✓ Once you hit submit you see the confirmation as below in **GREEN**
- ✓ You have now successfully registered with GE
- Preserve your SSO ID and credentials for further use

Please answer the following questions to request access to your selected applications.

Get secure access to GE applications in 3 easy steps

Dontonave a B2B account? Click here to register

Need Help

2

Sign in with your B2B

To browse the Application Catalog & request access

3

Select app from catalog &

Register for a B2B account

Sign In

There are no questions to answer, please click 'Submit' to continue.

Your application(s) were requested successfully! → Click here to close this window

## **Requesting clear orbit access**

#### Step 1

Open URL: <a href="https://registration.gepower.com/registration/">https://registration.gepower.com/registration/</a>

#### Step 2

- ✓ Click on Sign In
- ✓ Sign in with your SSO ID & Credentials

#### Step 3

- ✓ Once you Sign In
- ✓ You will be redirected to the Application Catalog
- ✓ Click on Supplier Apps
- ✓ Key-In "clear orbit" in search field
- ✓ Select Application Name by business aligned to
- ✓ Clear Orbit (Supplier Collaboration)
- ✓ Click on "+ Add"
- ✓ Once "Added" a pop-up with note "Request Access" will be visible
- ✓ Click on Request Access

#### Step 4

- ✓ Fill in the Questions for Clear Orbit (Supplier Collaboration)
- ✓ Provide purchase order number
- ✓ Enter Job Title
- Update telephone number and company name
- ✓ And Click Submit

All Applications Customer Apps	Supplier Apps Search by Name, Des	scription, Category or Keyw
Clear Orbit (Supplier Collaboration)	ClearOrbit Supplier Collaboration Tool Supporting Power , Energy Mgmt, and Oil business units	+ Add
to *	wality Module (Supplier Deviation Request [SDR]. Corrective	
o * Do you need access to the Q Action, or Request For Inforr O Yes O No Please add any additional de	vuality Module (Supplier Deviation Request [SDR], Corrective mation)* *	
co * Do you need access to the Q Action, or Request For Inforr ○ Yes ○ No Please add any additional de Quality Module Only, please	evality Module (Supplier Deviation Request [SDR], Corrective nation)* * stails needed to support your request. If this request is for the provide SQE name and/or buyer.	
Do you need access to the Q Action, or Request For Inforr O Yes No Please add any additional de Quality Module Only, please	evality Module (Supplier Deviation Request [SDR], Corrective mation)* * stails needed to support your request. If this request is for the provide SQE name and/or buyer.	
Do you need access to the Q Action, or Request For Inforr O Yes No Please add any additional de Quality Module Only, please	evality Module (Supplier Deviation Request [SDR], Corrective mation)* * stails needed to support your request. If this request is for the provide SQE name and/or buyer.	
Do you need access to the Q Action, or Request For Inforr O Yes No Please add any additional de Quality Module Only, please	Puality Module (Supplier Deviation Request [SDR], Corrective mation)* * stails needed to support your request. If this request is for the provide SQE name and/or buyer.	

**Classification:** Your request will be moved based on the workflow approval and once approved by clear orbit On boarding team and GE contact person/Buyer, An automated email notification will reach to your registered email ID and you will be able to access clear orbit Application with your SSO and Credentials

### **Forgot User ID**?

Purpose: Use this feature to retrieve your user id

Step 1: From the home page, click the "Forgot ID?" link –this will open a new page.

**Step 2:** Follow the instructions on screen to retrieve your account information. Enter your email address and click Submit

**Step 3:** If the system recognizes the email address you provided, you will see a confirmation message on screen and an email with the user account / id will be Sent.

An e-mail message with your USER ID(s) has been sent

Please close your browser window.

If no information is available for the entered email address, you will see this message:

No USER ID(s) were found for your specified e-mail address <u>Continue</u>

### **Forgot Password?**

Purpose: Use this feature to reset your password

**Step 1:** From the home page, click the "Forgot Password?" link –this will open a new page.

**Step 2:** Follow the instructions on screen: enter your user id and complete the security check. Click "**Submit**" to continue.



Forget User ID? Enter Email Address		
🖂 Enter Email Address		
Confirm Email Address		
Confirm Email Address		
	Submit	Cancel



**Step 3:** If the account is recognized, you will receive a confirmation message on screen (see picture to right). Additionally, an email will be sent to the account on file.

If there is no existing account **OR** the username you entered is locked / inactive, you will receive a message similar to those at right. If you feel you are getting these messages in error, use the "Need help?" feature to contact our team.

**Step 4:** An email is sent to your account on file. Click the "Reset your password" link. Note this link is temporary and will expire as indicated.

**Step 5:** You will be redirected to a new, secure window to update your password. Follow the instructions on screen and click "**Submit**"



Best regards

GE Power User Registration Team

Email message and secure temporary link for

	Please enter a new pastword	
	C Password	Must have 8 to 15 characters     Must centals lowercase letters
	(i) Verify Restword	Not certain stiesst 2 embedded numbers     Not begin and and with a letter     No special characters wough for "\"."
		Submit Cancel
r password reset	HEER HE	RYBERER

Confirmation message for successful password reset

**Step 6:** Once updated, you'll receive a "Success" message and be allowed to signin with your new password.



## P28A-AL-0002 Key Elements for SDR & RFI Process

A Nonconformance has to be notified to GE via SDR in ClearOrbit prior unit shipped as soon issue detected

P28A-AL-0002 lists all Nonconoformance material control requirement on following sections

3.2.22 Supplier Deviation Request (SDR) - A request initiated by the supplier to deviate from purchase order technical requirements (drawings, specifications, engineering instructions, etc.) or the approved qualification package

4.5.3 Supplier Deviation Request (SDR) Procedure (and all its subsections). Key Points:

The GE Supplier quality requirement is		General Electric International, Inc.	Document type: Acceptance Require	ed: Acceptance By:
	<b>8</b>	GE VAT Number: <u>VAT Registration Office Address:</u> General Electric International, Inc. 1 River Road, Schenectady, NY 12345 USA	Purchase Order Number 610579725	Rev. Number
	Supplier: STEEL F Adress: LIBRAM MONCL Email: agarcia@ Tel/Fax: 11528661 Contact:	Supplier: STEEL FAB DE MEXICO SA DE CV Address: LIBRAMENTO ELISEO, MENDOZA BERRUETO S N MOLCOVA, MONCLOVA, JOSLO MERCUENTO S N TA FRA: aparchatement of the second context: Context: Co		GE COMPANY 300 GARLINGTON ROAD GREENVILLE, SC-29615 United States
	GE Power Terms of P TO OBTAIN A COPY GOVERNING THIS			Submit invoice on-line using Order Settlement tool Portal.https://suppliercollaboration.ge-en ergy.com/scpiendeavour, Paper Invoices will be rejected,
	GE POWER SUPPLI	com/business-info/suppliers/document-library.html ER QUALITY REQUIREMENTS (P28A-AL-0002 REV M) APPLY	Phone: Email:	Carlos J.Nazario@ge.com
The GE Supplier quality requirement is Identified on EVERY PO         Image: Strategy of the strategy	ATTN: SUPPLIER!! 1 invoice to BILL TO a GE Gas Turbines (G	For prompt payment for blanket and service POs, send original ad a copy to: reenville/ LLC, PO Box 648, Greenville, SC 29602		

P28A-AL-0002 Key Elements

- **b.** The supplier may not ship any deviated part before it is in cleared or closed SDR stage. GE has the right to request additional inspections and tests beyond applied drawing and specifications to prove deviated part's form, fit and function prior to SDR disposition.
- c. The SDR must contain detailed description containment, probable source and proposed remedial action (when business directed) information as part of the initial submittal. Failure to supply all of the information as required may result in the SDR being returned to the Supplier for completion of the required information. If this rejection impacts fulfillment requirements charges may apply to the suppliers account.
- d. No repair shall be performed on a deviation prior to disposition by GE.
- e. SDRs are "one-time" exceptions to GE Power requirements.
- f. The approved SDR applies to only the PO's listed on the SDR.



- number of defects for the lot(s) of material
- specific purchase order numbers by part grouping
- serial numbers of the components
- estimated time to make correction(s)
- cost related issues

- When applicable:
- MLI Number
- IPS of the project
- Unit Serial Number
- Part Number
- PO Quantity

### **P28A-AL-0002 Key Elements for SDR & RFI Process**

### An SDR may have following disposition options:

- Repair: Is to bring nonconforming product into an acceptable condition by approved repair procedure.
- Rework: a nonconformance that will completely eliminate it and result in a characteristic that conforms completely to engineering requirements
- > **Use as is**: Accept with non conformance.
- Scrap: Nonconforming material that is not usable for its intended purpose and cannot be economically reworked or repaired

### Use of RFI (Request For Information)

 To request clarification on a GE drawing, specification or purchase order, to suggest drawing changes for improved quality or production or to point out drawing errors of administrative nature the supplier may submit a **Request for Information (RFI)**. No approvals to ship parts deviating from GE POs or Specifications can be granted through the RFI process. Any nonconformance part is only approved by SDR.

SDR and RFI are the only formal process/document that supplier have to use to communicate with GE to have a formal agreement on a Nonconformance or on a specification clarification



### Use Clear Orbit to track Nonconformnace



A	ttachments			Add At	tachment	
	Date	Name	Description			
-	Denete					
D	eviation Detail			Add D	eviation	
1	Deviation Deta	iils				
l	Deviatio	n Deta	ails 🧲			
-	Save Cance	l 🍄				
	Deviation Inf	ormation		Part	Related Informat	tion
	Deviation Qty	Deviation	Category		Assembly Sub-Com	ponent
	20 🖨	Fabricatio	n Error		llem #	Rev
	Commodity					
	Fabrications					

Clear Orbit - Supplier Collaboration Portal:
➢ On line tool with Supplier access
➢ System of record for disposition and CAPA
➢ Dashboard and tracking od cycle/repeats

## **Clear Orbit Overview**

### Getting to ClearOrbit

(https://suppliercollaboration.gepower.com/scp/endeavour/)

GE Power, GE Power, G	Oil & Ilabo	Gas, Er ration	nergy C	onnectio	ons & R	lene	wables						
Dashboard     GE Power, Oil & Gas,     Energy Connections &     Renewables Standard     Terms of Purchase	Q	Quality	PO	Shipme	ents Sel	ttlemer	nt						
Purchase Orders     Engineering Quality     Search Deviation     Request     Search Corrective Action     Search Direct Disposition	°	pen Devi	iations	De	eviation A 0 - 15	Aging 5 Days 0	16 - 30 Days	31 - 45 Days <u>0</u>	Above 45	Days	]		
Create Deviation Request Create Corrective Action Create Request For Information Bearch Request For Information Serialization Support Central On-Demand Reports	D	Deviation / Deviation Toda This V This M	Activity n Status lay Veek fonth	Initiated 0 0 0	Initial Re 0 0 0	eview	Dispo Complete	Rework Results	Quality R	eview	Cleared 0 0 0	Closed 0 0 0	-
Preferences Frequently Asked Questions Supplier Training Schedule	Dev	iation Sur	mmary	_		RFI	Summary		Direct	: Disposit	tion Summa	ary	
Tutorial GE Website Terms of Use Logout	Ini Ini Dis Re Qu	tiated tial Review sposition Co work Resul ality Review	r omplete Its w		0 0 0 0 0 0	Ini Clo Cor Ini	itiated osed rective Action Sum	1 0 mary 0	Initia Engir Quali Quali	ted Ieer Review ty Review ty Leader	w Review		0 0 0
	Cle	eared osed			0 3	Re Ap	jected proved	0					

To download Clear Orbit user tutorials, training schedule, how to documents and more (requires SSO ID), click here:

- Clear Orbit <u>https://www.ge.com/gas-power/clear-orbit-requestinfo</u>
- Clear Orbit <u>https://www.ge.com/gas-power/clear-orbit-deviationrequest</u>
- Clear Orbit <u>https://www.ge.com/gas-power/clear-orbit-correctiveactions</u>

If you are unable to download the tutorials, please inform your Sourcing or Supplier Quality contact in GE

# eSourcing Support Contact(s)

If you still face any issues; Please contact L1 eSourcing Helpdesk

- ✓ T: (866)-770-5248 Option 2
- ✓ Email: psesourps@ps.ge.com
- ✓ Visit us @ <u>https://app.sc.ge.com/sites/1564108/portal/1043018</u>

### **Escalation Point of Contact**

- ✓ Kennedy, Andrew <u>-andrew.kennedy@ge.com</u>
- ✓ G, Karthikeyan <u>-Karthikeyan2.G@ge.com</u>

Required (Mandatory) Information for us to assist you further while sharing information

- ✓ User ID/SSO ID
- ✓ Purchase Order Number
- ✓ Contact Phone Number#
- ✓ Available time of Contact
- ✓ Screen Shot of Error